

SVILUPPI

PROFILI

ANGOLARI		" L "	" U "
50x50x3 =	95	80x40x3 =	115
xH =	93	xH =	113
x5 =	91	x5 =	111
x6 =	89	x6 =	109
55x55x4 =	103	80x50x3 =	125
x5 =	101	x4 =	123
x6 =	99	x5 =	121
60x60x4 =	113	x6 =	119
x5 =	111	100x50x3 =	145
x6 =	109	x4 =	143
70x70xH =	133	x5 =	141
x5 =	131	x6 =	139
x6 =	129	100x80x4 =	173
80x80x4 =	153	x5 =	171
x5 =	151	x6 =	169
x6 =	149	120x60x4 =	173
x8 =	145	x5 =	171
90x90xH =	173	x6 =	169
x5 =	171	120x80xH =	193
x6 =	169	x5 =	191
100x100x4 =	193	x6 =	189
x5 =	191		
x6 =	189		
x8 =	185		



SVILUPPI

PROFILI

ANGOLARI				" L "				" U "			
20	x	20	x 3 = 35	30	x	20	x 3 = 45	15	x	30	x 15 x 3 = 49
		x	4 = 33			x	4 = 43			x	4 = 44
		x	5 = 31	40	x	20	x 3 = 55	20	x	40	x 20 x 3 = 69
25	x	25	x 3 = 45			x	4 = 53			x	4 = 64
		x	4 = 43			x	5 = 51			x	5 = 60
		x	5 = 41	40	x	30	x 3 = 65	25	x	50	x 25 x 3 = 89
30	x	30	x 3 = 55			x	4 = 63			x	4 = 84
		x	4 = 53			x	5 = 61			x	5 = 80
		x	5 = 51	50	x	25	x 3 = 70			x	6 = 76
		x	6 = 49			x	4 = 68	40	x	50	x 40 x 3 = 119
35	x	35	x 3 = 65			x	5 = 66			x	4 = 114
		x	4 = 63			x	6 = 64			x	5 = 110
		x	5 = 61	50	x	30	x 3 = 75			x	6 = 106
		x	6 = 59			x	4 = 73	30	x	60	x 30 x 3 = 109
40	x	40	x 3 = 75			x	5 = 71			x	4 = 104
		x	4 = 73			x	6 = 69			x	5 = 100
		x	5 = 71	60	x	30	x 3 = 85			x	6 = 96
		x	6 = 69			x	4 = 83	40	x	80	x 40 x 4 = 144
45	x	45	x 3 = 85			x	5 = 81			x	5 = 140
		x	4 = 83			x	6 = 79			x	6 = 136
		x	5 = 81	60	x	40	x 3 = 95	50	x	100	x 50 x 4 = 184
		x	6 = 79			x	4 = 93			x	5 = 180
						x	5 = 91			x	6 = 176
						x	6 = 89				

